

HISTORIC AMERICAN BUILDINGS SURVEY  
INDEX TO PHOTOGRAPHS

HABS  
NJ,  
11-TRET,  
26-

Trenton House Hotel  
Trenton  
Mercer County  
New Jersey

HABS No. NJ- 960

E. Kenneth Hoffman, Photographer, August 1987

- NJ-960-1 View of building looking across the intersection of North Warren and East Hanover Streets. Camera facing southeast.
- NJ-960- 2 View of East Hanover Street elevation of original section of the hotel. (North Warren Street to right). Camera facing south.
- NJ-960- 3 View of East Hanover Street (north) elevation of hotel. 1869 addition. Camera facing south.
- NJ-960- 4 View of East Hanover Street (north) elevation of hotel. 1869 addition. Camera facing south.
- NJ-960- 5 View of East Hanover Street (north) elevation of hotel. 1871 addition. Camera facing south.
- NJ-960- 6 View of East Hanover Street (north) elevation of hotel. 1871 addition. Camera facing south.
- NJ-960- 7 View of East Hanover Street (north) elevation of hotel. 1871 addition. Camera facing south.
- NJ-960- 8 View from within hotel's rear wing, across enclosed courtyard/service yard area, toward rear of annex building fronting North Warren Street. Camera facing west.
- NJ-960- 9 Interior, guest room on the second floor, fronting North Warren Street (1871 section). Camera facing southeast.

TRENTON HOUSE HOTEL  
HABS No. NJ - 960 (page 2)  
INDEX TO PHOTOGRAPHS

- NJ-960-10 Interior, guest suite on the second floor, fronting East Hanover Street, 1871 wing. Camera facing south-southeast.
- NJ-960-11 Interior, guest suite on the second floor. Plaster ceiling medallion at top of photo. Camera facing southwest.
- NJ-960-12 Interior, guest suite on the second floor. Plaster ceiling with stencilled border design, plaster molded cornice, and window frame detail.
- NJ-960-13 Interior, hallway to adjoining second floor suites, taken from main hall of 1871 wing of hotel. Camera facing north.
- NJ-960-14 Interior, stairway in 1871 wing of hotel. Third floor landing. Camera facing south.
- NJ-960-15 Interior of elevator cab grillwork.
- NJ-960-16 Interior, fragments of pressed metal ceiling at first floor rear.
- NJ-960-17 Interior, molded plaster cornice and overdoor decoration found in a closet on the first floor. May have been part of a dining room at the turn of the century.
- NJ-960-18 Interior, only surviving mantel in the hotel, third floor.
- NJ-960-19 Historic Photograph: Trenton House Hotel, ca. 1890. Picture collection, Trenton Free Public Library.